

LCD DIGITALE TERMOMETRO IGROMETRO OROLOGIO CALENDARIO STAZIONE METEO TEMPERATURA



Feature:

Measuring temperature range: 0-50°C (32°F-122°F)

Measuring humidity range: 20%-99%

Display: max/min temperature and humidity records

Calendar: 2000-2099year

OPERATION:

Press MODE one time to view calendar

Press MODE one more time to the view the alarm time

SETTING THE TIME

Press and hold MODE for 3 seconds to enter the time setting mode.

The hours digits are blinking and can be set by pressing up or DOWN for setting hour.

Press MODE again:

The minute digits are blinking and can be set by pressing up or DOWN for setting minute.

Alarm ON/OFF

Press UP to turn alarm on/off

Max/Min

Press Max/Min to view max temperature and humidity record.

Press Max/Min again to view min temperature and humidity record.

12/24 format hour

Press UP for three seconds to switch 12 or 24 format hour time display.

Temperature display format

Press DOWN to switch c/f display

SNOOZE/LIGHT

In alarm to press SNZ/LIGHT for snooze mode

Press SNZ/LIGHT to turn color back light.

Package includes:

1x Instruction

1x Hygrometer